





1. Fully charge the 8068 by using USB A to Type C cable.



2. Press and hold the on/off button for 5 seconds to switch the instrument on/off.



3. During the instrument's 'start up', the 8068 will automatically zero.

